


SEWING MACHINE TABLE

COMFORT 9

СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK






ОБОЗНАЧЕНИЕ









EVEN SURFACE

РОВНАЯ ПОВЕРХНОСТЬ






010001 1x	010002 2x	010004 1x	010006 1x
010007 1x	010011 2x	010012 2x	010013 2x
010015 1x	010020 2x	010026 1x	010028 1x
010030 1x	010033 1x	010034 1x	








020001  2x	020003  2x	020004 2x 	020005 2x 	020006  2x
---	---	--	--	---

020011 2x 	020012 2x 	020018 4x 	10x 020019 	020020 4x 	020034 4x 
--	--	--	---	---	--

3x 020013 CR 	3x 020013 CL 
--	---

3x 020015 DR 	3x 020015 DL 
---	--

030001 3 * 16 16x 	030002 3,5 * 16 36x 	030003 6,2 * 50 14x 	030033 4,2 * 13 56x 	030006 2,9 * 13 8x 
--	--	--	---	---

030008 φ4 4x 	030009 M4 * 20 4x 	030011 φ15 14x 	030012 φ18 6x 	030013 L = 35 6x 	030014 φ15 h12 6x 	030028 3,9*16 8x 
---	--	---	--	--	--	---

030015 φ8 * 30 8x 	030016 φ8 * 30 4x 	030017 φ15 h10 4x 	030061 4x M 10 	030060 φ 10 4x 	030031 φ 10 s2,5 4x 
--	--	--	---	---	--

1x 050001 	1x 050002 	1x 050004 
1x S4 	1x 050003 	



S4 *


S5

S10
S12



2 8x 030011
8x 03003

1 030002
6x
020013 CR 3x





3 4x 030061
4x 030031
4x 030060
4x 020034




1 020013 CL 3x
030002 6x

4 6x 030011
6x 030003

4

* Входит в комплект стола.
Included into table set.

6 020011
2x 
8x 
 030002

5 030008 030009
4x  **4x** 
2x 
 020006


7 020003

2x 
6x 
 030033

010007
 010015



8 **4x** 
 030006
2x 
 020004

010001



9 
 030015
4x

10 030013
6x 

010015

11 **6x** 
 030014
6x 
 030012

010007

14 020005
2x 
4x 030001


12 **8x**  030028
12x  030002




4x 020018

13 020012 030006
2x  **4x** 

17 24x 030033
 6x 020019

16 16x 030033
 4x 020019

15 020001 030033
 2x 6x




21
 1x 010034

20 4x 020020

18 030033
 2x 1x 050001

19
 1x 050003
 1x 050002 2x 030033



22

4x 030001


2x 020015 DR

030016 **24**

4x

25


4x 030017



22

4x 030001

2x 020015 DL



26


1x 020015 DL

2x 030001

27

4x 030002



1x 050004



26

2x 030001

1x 020015 DR



СПАСИБО ЗА ПОКУПКУ!

*скачать инструкцию
по сборке,
посмотреть
видео по установке
подъемного механизма*



<https://www.shveystol.ru>

*приобрести
аксессуары к столам*



оставить отзыв

 SHVEYSTOL_76

https://vk.com/shveystol_76

 @SHVEYSTOL

t.me/shveystol



ОСТАЛИСЬ ВОПРОСЫ?

8 - 915 - 960 - 93 - 66

